

Disclosure on the boilers:

Boiler #1: The bearings in the fan motor have deteriorated beyond repair so the motor needs to be replaced.

Boiler #2: A large portion of the furnace refractory has fallen out and is in need of repair.